



Intel[®] Memory and Storage Tool (Intel[®] MAS) Graphic User Interface (GUI)

Release Notes

May 2024

Revision: 019US



Notice: This document contains information on products in the design phase of development. The information here is subject to change without notice. Do not finalize a design with this information.

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software, or service activation. Learn more at intel.com, or from the OEM or retailer.

No computer system can be absolutely secure. Intel does not assume any liability for lost or stolen data or systems or any damages resulting from such losses.

You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document. The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

Tests document performance of components on a particular test, in specific systems. Differences in hardware, software, or configuration will affect actual performance. Consult other sources of information to evaluate performance as you consider your purchase. For more complete information about performance and benchmark results, visit <http://www.intel.com/performance>.

Cost reduction scenarios described are intended as examples of how a given Intel-based product, in the specified circumstances and configurations, may affect future costs and provide cost savings. Circumstances will vary. Intel does not guarantee any costs or cost reduction.

Results have been estimated or simulated using internal Intel analysis or architecture simulation or modeling and provided to you for informational purposes. Any differences in your system hardware, software or configuration may affect your actual performance.

Intel does not control or audit third-party benchmark data or the web sites referenced in this document. You should visit the referenced web site and confirm whether referenced data are accurate.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel, the Intel logo, Intel Core, and Intel Optane are trademarks of Intel Corporation or its subsidiaries.

*Other names and brands may be claimed as the property of others

Copyright © 2022, Intel Corporation. All Rights Reserved.

Contents

1	Intel® Memory and Storage Tool (Intel® MAS) (GUI)	9
----------	----------------------------------------------------------------	----------

Tables

Table 1-1. List of Intel® Optane™ Solid State Drives.....	9
Table 1-2. List of Intel® Optane™ Memory Devices.....	9
Table 1-3. Intel® Optane™ Memory H10 Revision History.....	9
Table 1-4. Intel® Optane™ SSD 905P/900P Revision History.....	10
Table 1-5. Intel® Optane™ SSD P4800X/P4801X Revision History	10
Table 1-6. Intel® Optane™ SSD P5800X Revision History	11



Revision History

Software Revision	Description	Date
2.5	Changes in revision 2.5 of the Intel® MAS GUI include: <ul style="list-style-type: none">Windows installer bug fix	May 2024
2.3	Changes in revision 2.3 of the Intel® MAS GUI include: <ul style="list-style-type: none">Added E2010650 firmware update for Intel® Optane™ DC P4800X/P4801X Series and Intel® Optane™ SSD 905P/900P SeriesAdded E2010611 firmware update for Intel® Optane™ DC D4800X SeriesAdded G004-0553 firmware update for Intel® Optane™ H20 SeriesMitigates security vulnerability	August 2023
2.2	Changes in revision 2.2 of the Intel® MAS GUI include: <ul style="list-style-type: none">Added L0310600 firmware update for Intel® Optane™ P5800X SeriesRemoved Solidigm* related links and text from the installer UI, Intel® MAS UI, and Intel® MAS CLI	December 2022
2.1	Changes in revision 2.1 of the Intel® MAS GUI include: <ul style="list-style-type: none">Added firmware updates for hybrid productsHide Command Line Interface (CLI) properties when they are not applicableFixed Intel® MAS GUI crash that occurred with certain Intel® Rapid Storage Technology (Intel® RST) RAID configurations	July 2022
2.0	Changes in revision 2.0 of the Intel® MAS GUI include: <ul style="list-style-type: none">New UI for Intel® MASRemoved Intel® NAND Flash Memory only featuresFirmware Update to E2010603 for Intel® Optane™ P4800X/P4801X SeriesFirmware Update to E2010603 for Intel® Optane™ 905P/900P Series	May 2022
1.12	Changes in revision 1.12 of the Intel® MAS GUI include: <ul style="list-style-type: none">Resolved firmware update for Intel® Optane™ P5800X SeriesAdded namespace overprovisioning supportCorrected the capacity calculation displayed in drive information	December 2021

Software Revision	Description	Date
1.10 v.2	Changes in revision 1.11 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Firmware Update to E2010600 for Intel® Optane™ P4800X/P4801X Series for ESXi* • Firmware Update to L0310200 for Intel® Optane™ P5800X Series for ESXi* • Firmware Update to 2CV10201 for D7-P5500/P5600 Series • Firmware Update to JCV10200 for D7-P5510 Series • Firmware Update to ACV10200 for D5-P5316 Series • Added support for Windows* 11, Windows Server* 2022, ESXi* 7.0.3, RHEL* 8.3, 8.4, CentOS* 8.3, 8.4 • Fixed aggregation threshold error message • Resolved firmware update for some Intel® Optane™ SSD P4800X/P4801X Series products 	October 2021
1.10	<ul style="list-style-type: none"> • Firmware Update for Intel® Optane™ SSD P4510, P4511, P4610 and P4618 Series 	September 2021
1.9	Changes in revision 1.10 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Firmware Update for Intel® Optane™ SSD P4800X/P4801X Series for Windows and Linux* • Firmware Update for Intel® Optane™ SSD P4510, P4610 and P4618 Series • Fixed bug of drive temperature reporting unknown if above 70 degrees Celsius 	August 2021
1.8	Changes in revision 1.9 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Firmware Update for Non-Opal SKUs for P4510, P4610 and P4618 Series to VDV10182 • Firmware Update to L0310200 for Intel® Optane™ SSD P5800X Series (400GB, 800GB, 1.6TB). Update for Windows* and Linux* only • Changed text for Firmware Update button 	June 2021
1.7	Changes in revision 1.8 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Allow firmware update for Intel Optane Memory H Series products when cache is enabled with Intel® Rapid Storage Technology (Intel® RST) Driver 17.9 and above • Fixed issue of diagnostic scan always performing quick scan • Updated Intel® MAS license 	May 2021



Software Revision	Description	Date
1.6	Changes in revision 1.7 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Added ability to show Self-Monitoring and Reporting Technology (SMART) health log pages on non- Intel® SSD • Fix to allow H10 Series to update firmware individually if update is available for one component only • Update performance booster behavior to fully support 670P series • Updated handling of Secure Erase* feature with Intel® RST Driver • Show Intel® RAID members in GUI when drives setup as MegaRAID*. Added support for select MegaRAID* adaptors • Fixed issue of scheduled optimize sessions not being removed from Windows* scheduled list • Firmware Update for Intel® Optane™ P4320, P4420 Series to 3DV10131 & P4326 Series to 8DV10561 	April 2021
1.5	Changes in revision 1.6 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Fix for security state being incorrectly reported as Opal Activated on Intel® Optane™ SSD 905P. • Display correct “Use Firmware Update Tool” message for applicable drives and firmware when attempting to update firmware. • Fix issue with Optimizer failing after Windows* 20H2 update. • Updated FW version for few products 	February 2021
1.4	Changes in revision 1.5 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Removed Intel® SSD Optimizer functionality for Intel® Optane™ technology products (Feature is only supported on Intel® NAND Flash Memory based products) • SMART health log page parser updates • Added missing firmware update for 320 Series • Removed stale update notes in settings section of GUI • Updated Intel® Optane Memory H20 with Solid State Storage product family names • Added missing identify controller fields in support of Intel® SSD 670p Series 	January 2021
1.4	<ul style="list-style-type: none"> • FW information updated for Intel® SSD S3300 	December 2020
1.3	Changes in revision 1.4 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Only enable system tuner feature for SATA products • Fixed issue showing enabled firmware update button regardless of firmware status • Added missing firmware update for 256 GB 660p Series SKU • Additional tweaks for progress and life remaining bar “look and feel” • Updated wording for CVE document (see Intel Advisory INTEL-SA-00362) 	November 2020

Software Revision	Description	Date
1.2	Changes in revision 1.3 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Fix Typo in Intel® MAS Secure Erase* feature and fixed status of Secure Erase* • Added firmware (FW) for Intel® Optane™ Memory H10 with Solid State Storage to FW G002-0440 • SMART attribute description updates • Fixed issue with Optimizer scheduler showing incorrect last run date • Fixed issue incorrectly blocking Optimizer on some S4510 Series drives • Fixed issue incorrectly retrieving identify namespace data on systems with Microsoft* NVMe* driver 	October 2020
1.1	Changes in revision 1.2 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Intel® Optane™ SSD P4800X Series FW update to FW 485 (for ESXi*) • Updated Intel® SSD D5-P4320 and Intel® SSD D5-P4326 firmware to 3DV10130 and 8DV10560 respectively • Fixed incorrect health status • Added Health data and value in Resources for each language • Fixed alignment of drive list • Used Native language names • Added “Give feedback” string • Fixed incorrect health status calculation that caused preemptive health warning • Fixed issue of Mansion Beach drive FW update failures from E2010325 	August 2020
1.0.5	Changes in revision 1.1 of the Intel® MAS GUI include: <ul style="list-style-type: none"> • Updated UI presentation and theme • Updated splash screen to approved Intel image • Updated temperature bar as accepted range (maximum is 70°C) • Temperature bar is now a gradient. As temperature reaches maximum bar will increasingly show red color • Updated estimated life remaining to reflect SMART information percentage used field • Updated setting popup window to align with core UI • Fixed BSOD related to performance booster feature • Fixed tool crash with feature dropdown menu • Added ability to copy/past basic drive information in drive summary page • Fixed issue with incorrect temperature values reported on non-supported drives • Fixed URL link pointing to latest tool download page • This revision added a firmware update for Intel® Optane™ Memory, Intel® Optane™ SSD 905P/900P, Intel® Optane™ SSD P4800X/P4801X, Intel® SSD D3-S4510/D3-S4610, DC S3100, DC P4101, E 6100p, E 5400s, E 5100s, Pro 7600p, Pro 6000p, Pro 5450s, Pro 5400s, 760p, 660p, and 540s. 	July 2020



Software Revision	Description	Date
1.0	<ul style="list-style-type: none">• This is the first revision of the Intel® MAS Tool, GUI• This version of the tool contains both a Graphical User Interface (GUI) and a Command Line Interface (CLI) with the functionality to manage Client and Datacenter Intel® SSD and Intel® Optane™ Memory. See the User Guide for more information.	April 2020

Note: If you purchased your Intel® SSD from an OEM, your firmware version may have a different naming sequence. Contact your local OEM representative for the latest firmware revisions.

1 Intel® Memory and Storage Tool (Intel® MAS) (GUI)

Table 1-1. List of Intel® Optane™ Solid State Drives

Model	Latest Firmware Version
Intel® Optane™ SSD DC P5800X	L0310600
Intel® Optane™ SSD DC P4800X/P4801X	E2010650
Intel® Optane™ SSD DC D4800X	E2010611
Intel® Optane™ SSD P1600X	U5110550
Intel® Optane™ SSD 905P/900P	E2010650
Intel® Optane™ SSD 800P	K4110440

Table 1-2. List of Intel® Optane™ Memory Devices

Model	Latest Firmware Version
Intel® Optane™ Memory H20	G004-0553
Intel® Optane™ Memory H10	G003-0440
Intel® Optane™ Memory M10	K4110440
Intel® Optane™ Memory	K3110310

Table 1-3. Intel® Optane™ Memory H10 Revision History

Date	Revision	Description
September 2020	G002-0440	This firmware version has following fixes: <ul style="list-style-type: none"> Complaint with the 10th Generation Intel® Core™ mobile processor Platform



Table 1-4. Intel® Optane™ SSD 905P/900P Revision History

Date	Revision	Description
Aug 2023	E2010650	This firmware version has the following fixes. <ul style="list-style-type: none"> • Mitigates security vulnerability, see Intel Advisory INTEL-TA-00758
May 2022	E2010603	This firmware version has the following fixes. <ul style="list-style-type: none"> • Fix Windows Server* 2022/Windows* 11 certification related I/O test issue
July 2020	E2010480	This firmware version has the following fixes. <ul style="list-style-type: none"> • Fix for drive fails to set correct Native Maximum Logical Block Addressing (LBA) when forcing maximum address capacity to smaller one • Fix for media errors and E2E error increments after coming back to the native capacity • Fix for drive sometimes fails PCI Express* (PCIe*) training during reboots resulting in reduced link width or speed • Fix link width degrades during link disable/enable on some platforms • Fix for serial number is all zeroes after U.2 drive Hot Plug* operation • Fix for Quality Reliability Test encountered Cold ECC Failure • "Mitigates security vulnerability (see Intel Advisory INTEL-SA-00362)"

Table 1-5. Intel® Optane™ SSD P4800X/P4801X Revision History

Date	Revision	Description
Aug 2023	E2010650	This firmware version has the following fixes. <ul style="list-style-type: none"> • Mitigates security vulnerability, see Intel Advisory INTEL-TA-00758
May 2022	E2010603	This firmware version has the following fixes. <ul style="list-style-type: none"> • Fix Windows Server* 2022/Windows* 11 certification related I/O test issue
August 2021	Windows*/Linux* – E2010600	Intel® Optane™ SSD P4800X/P4801X updates to firmware E2010600 for Windows*/Linux* (ESXi* version will be released later)
August 2020	Windows*/Linux* - E2010485 ESXi* - E2010485	Intel® Optane™ SSD P4800X Series FW update to FW 485 (for ESXi*)
July 2020	Windows*/Linux* - E2010485 ESXi* - E2010475	Intel® Optane™ SSD P4800X 375 GB AIC SKU now supported for upgrade
May 2020	Windows*/Linux* - E20104851 ESXi* - E20104751	This revision adds the following firmware updates for Intel® Optane™ SSD P4800X/P4801X: <ul style="list-style-type: none"> • Windows*/Linux* - E2010485 • ESXi* - E2010475 <p>Note: 1. P4800X 375 GB AIC SKU with firmware E2010211 will not support upgrade firmware to E2010475 or E2010485, this is targeted for a future release.</p> <ul style="list-style-type: none"> • Minor Bug fixes and enhancements
December 2019	E2010435	The following changes are included in this firmware update: <ul style="list-style-type: none"> • QAN 9871

Date	Revision	Description
February 2018	E2010324 (375 GB) EB3B0306 E2010325 (750 GB) EB3B0309	<p>The following changes are included in this firmware update:</p> <ul style="list-style-type: none"> • Bug fixes from previous firmware on 375 GB (from FW: E2010320) • Note that 750 GB was qualified on firmware E2010325. There is no maintenance release past that FW. Additionally, there is limited applicability of this firmware on quality samples. Reach out to Intel representative if your 750-GB samples are on earlier revision than FW E2010325.

Table 1-6. Intel® Optane™ SSD P5800X Revision History

Date	Revision	Description
November 2022	Windows*/Linux* – L0310600	<p>This firmware version has the following fixes.</p> <ul style="list-style-type: none"> • Fix for multiple “Firmware Activation Without Reset” use cases • Fix for “Format Progress Indicator” display issue • Fix for “NVMe format over NVMe-MI failure” issue • Fix for “Device-Self-Test maybe rejected” issue
May 2022	L0310200	<p>This firmware version has the following fixes.</p> <ul style="list-style-type: none"> • Add “Firmware Activation Without Reset” feature • Fix SMART log page issue for sanitize over NVMe-MI* issue